


Two-set spanners




Material	PA66
Ambient temperature range	-40℃ ~ +90℃




Apply to 4.0 series connectors

Tool application diagram

Push in





The hook will be unlocked when the spanner comes to the end.



Disconnection

Turn the spanner to fasten the screw cap


## SC-S002 Stripping Tool



### MAIN SPECIALITY

>> Suitable for stripping the cable of 2.5~6.0mm<sup>2</sup> (AWG10-14)

>> Suitable for solar system installation site, flexible application




## SC-P003 SC-P004 Crimping Tool




### MAIN SPECIALITY

>> Suitable for crimping the cable of 2.5~6.0mm<sup>2</sup> (AWG10-14)

>> Suitable for solar system installation site, flexible application



SC-P003



SC-P004